

Inspection Photos

Loc: 437659

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 2/4/2025

County: LINCOLN



Inspection Photos



Photo 1. Drone aerial photo facing northeast along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:437659 | Date: 2/4/2025

Inspection Photos



Photo 2. Drone aerial photo facing north along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:437659 | Date: 2/4/2025

Inspection Photos



Photo 3. Facing east along the road toward the fenced location.



Inspection Photos



Photo 4. Facing east toward the location. There are areas of perennial vegetation but additional seeding needs to be performed to help promote more growth.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:437659 | Date: 2/4/2025

Inspection Photos




Photo 5. Facing south toward the location. There are areas of perennial vegetation but additional seeding needs to be performed to help promote more growth.



Inspection Photos




Photo 6. Center of the location facing north. There are areas of perennial vegetation but additional seeding needs to be performed to help promote more growth.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:437659 | Date: 2/4/2025

Inspection Photos




Photo 7. Facing north toward the reference area which consists of native Blue grama dominate grassland.

