

Inspection Photos

Loc: 437862

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 2/4/2025

County: LINCOLN



Inspection Photos



Photo 1. Facing north along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:437862 | Date: 2/4/2025

Inspection Photos



Photo 2. Facing northwest along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



Inspection Photos



Photo 3. Facing west toward the location. Perennial vegetation has not established and the location needs to be reseeded.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:437862 | Date: 2/4/2025

Inspection Photos




Photo 4. North side of the location facing south.



Inspection Photos



Photo 5. West side of the location facing east.



Inspection Photos



Photo 6. South side of the location facing north.



Inspection Photos



Photo 7. Facing north toward the reference area which consists of native Blue grama dominate grassland.

