

Inspection Photos

Loc: 431583

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 2/4/2025

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



Inspection Photos



February 4, 2025
+38.647399, -103.381742
ECMC

Photo 2. Facing southwest along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431583 | Date: 2/4/2025

Inspection Photos



Photo 3. Facing south toward the location. Perennial vegetation has not established and the location needs to be reseeded.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431583 | Date: 2/4/2025

Inspection Photos



Photo 4. West side of the location facing east.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431583 | Date: 2/4/2025

Inspection Photos



Photo 5. South side of the location facing north.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431583 | Date: 2/4/2025

Inspection Photos



Photo 6. East side of the location facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431583 | Date: 2/4/2025

Inspection Photos



Photo 7. Facing northwest toward the reference area which consists of native Blue grama dominate grassland.

