

# Inspection Photos

February 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 333767

Inspection Document #: 714001782

La Plata County, CO

Township: NWSW 15 34N 8W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: McCaw 34-15 2, 4  
Location ID: 333767



Photo 1. View of the well pad from the access point facing center.





2/3/25  
336° NW



**Photo 2:** Separator labels have deteriorated and are no longer legible.



Inspection Photos  
Location Name: McCaw 34-15 2, 4  
Location ID: 333767



**Photo 3.** Stormwater issues persist in the southern interim reclamation area. BMPs have not been installed correctly.



Inspection Photos  
Location Name: McCaw 34-15 2, 4  
Location ID: 333767



2/3/25  
2° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Northern interim reclamation area composed of Western Wheatgrass, Sand Dropeed and Broom Snakeweed.

API #: 067-08958, 09563



Inspection Photos  
Location Name: McCaw 34-15 2, 4  
Location ID: 333767



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Juniper, Sagebrush and Smooth Brome.

API #: 067-08958, 09563