

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/28/2025

Submitted Date:

01/31/2025

Document Number:

713601835

**FIELD INSPECTION FORM**

Loc ID 321614 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 17180

Name of Operator: CITATION OIL &amp; GAS CORP

Address: 14077 CUTTEN RD

City: HOUSTON State: TX Zip: 77069

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Steffy Goncalves		SGoncalves@cogc.com	
Citation		ENV-CODNR@cogc.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207522	WELL	TA	09/01/2020	OW	017-06457	RHOADES 13-35 1	RI

**General Comment:**

This is a follow up inspection of the RHOADES 13-35 #1 wellsite.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	The well sign still remains fallen over. Previous CA was not completed.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	There is an electric utility that has fallen over by the well sign. This needs to be removed or properly installed.		
Corrective Action:		Date:	
Type	STORAGE OF SUPL		
Comment:	The barrel and container have been removed.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: There was no stained soils observed at the surface around the wellsite. There was a form 27 subitted for investigation and remediation of previous spill.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: The culvert at the beginning of the access road is damaged and needs to be repaired or replaced.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 02/14/2025

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404077673	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900555">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900555</a>
713601836	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900529">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6900529</a>