

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Photo # 4088 Entrance to location



Photo # 4085 Location

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Photo # 4089 Location



Photo # 4092 Location

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Feb 4, 2025 at 1:06:28 PM
+39.544380, -108.284313 ±0.96m



Feb 4, 2025 at 1:16:43 PM
+39.544666, -108.284636 ±4.89m

Photo # 4100 Location

Photo # 4107 Location

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Photo # 4110 NE corner of location



Photo # 4111 SE corner of location

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Photo # 4112 SW corner of location



Photo # 4113 NW corner of location

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Photo # 4114 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 4115 Failure to minimize erosion & transport of sediment off location/insufficient BMP's

Inspection/Audit Photos

Location: CHEVRON USA INC SKINNER RIDGE-66S98W/12NWSW (SKINNER RIDGE #698-12-1)

Location ID: 324306

Date: 02/4/2025



Photo # 4117 Failure to minimize erosion & transport of sediment off location/insufficient BMP's



Photo # 4119 Failure to minimize erosion & transport of sediment off location/insufficient BMP's