

## Inspection/Audit Photos

Location: QB ENERGY P6-11-36 (MESA 20 PAD)

Location ID: 418691

Date: 02/5/2025



Photo # 4185 Entrance to location



Photo # 4184 Location



## Inspection/Audit Photos

Location: QB ENERGY P6-11-36 (MESA 20 PAD)

Location ID: 418691

Date: 02/5/2025



Photo # 4186 Location



Photo # 4193 Location





## Inspection/Audit Photos

Location: QB ENERGY P6-11-36 (MESA 20 PAD)

Location ID: 418691

Date: 02/5/2025



Photo # 4201 No tank battery signage



Photo # 4218 Location

## Inspection/Audit Photos

Location: QB ENERGY P6-11-36 (MESA 20 PAD)

Location ID: 418691

Date: 02/5/2025



Photo # 4219 NW corner of location



Photo # 4220 SW corner of location



## Inspection/Audit Photos

Location: QB ENERGY P6-11-36 (MESA 20 PAD)

Location ID: 418691

Date: 02/5/2025



Photo # 4221 SE corner of location



Photo # 4223 NE corner of location

## Inspection/Audit Photos

Location: QB ENERGY P6-11-36 (MESA 20 PAD)

Location ID: 418691

Date: 02/5/2025



Photo # 4208 Open ended load line



Photo # 4211 PRV vent line on tank heater does not comply with CECMC pressure safety device rules