

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 2999 From entrance to location



Photo # 3000 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 3001 Location

Photo # 3002 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 3003 Location



Photo # 3004 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 3005 Location

Photo # 3006 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 3007 Location



Photo # 3008 Staining near separator

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 3009 Staining near separator



Photo # 3010 SNYDER A10 cellar lacks wildlife egress

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER A Pad

Location ID: 311651



Photo # 3011 SNYDER A10 cellar lacks wildlife egress