

GM 31-17: Rilling at Entrance to Pad Has Been Graded and Bar Ditch Installed on North Side of Entrance



Before



After

GM 31-17: Sediment Basin on SE Edge of Location Has Been Cleaned Out; Rock Protection Added to All Inlets and Outlets



Before



After

GM 31-17: Rock Protection Added to Rills Below Sediment Basin in SE Corner of Location. Note 3 Additional Sediment Traps Below



Before



After

GM 31-17: Outlet of Sediment Trap on SE Edge of Location Has Been Repaired and Protected with Rock Armor



Before



After

GM 31-17: Rills and Gully Erosion Repaired. Note Series of Rock Check Dams and Rock Outlets Installed Above and Below Sediment Basin



Before



After

GM 31-17: Rill Erosion on Interim Reclaim Area in SE Portion of Pad Has Been Repaired.



Before



After

GM 31-17: Unmarked Anchor Has Been Removed



Before



After

GM 31-17: Multiple Layers of BMPs Below SE Corner of Pad. Rock Check Dams, Hydro Seed & Mulch, Straw Wattles, Multiple Sediment Traps, Rock Protection on Inlets / Outlets, Vegetative Buffer

