

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/06/2025

Submitted Date:

02/09/2025

Document Number:

708905711**FIELD INSPECTION FORM**Loc ID 452566 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**22 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
TEP		COGCCInspectionReports@terraep.com	
Toews, Wesley		wtoews@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
452559	WELL	PR	07/26/2018	GW	045-23734	FEDERAL RU 513-17	PR

**General Comment:****CECMC Inspection/Audit Report Summary**

On 02/06/2025 at approximately 12:23 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC FEDERAL RU 513-17

Location # 452566 in Garfield County Colorado.

Location is within Black Bear Habitat area &amp; in close proximity to High Priority/Density Habitat areas.

While there, I observed workover operations on the FEDERAL RU 513-17 well API # 05-045-23734

This is a summary of inspection/audit report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Rig sign at intersection of Beaver Creek Road & Rifle-Rulison Road		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Rig signs at intersections along lease road		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Rig sign at intersection of Beaver Creek Road & Start of lease road		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Tank label on frac tank damaged & some info is becoming illegible - please refer to photo log  Spoke with TEP consultant on location & he said they'd get a new label on the tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911/970-285-9377	
Corrective Action:		Date: _____

**Good Housekeeping:**

Type	OTHER		
Comment:	Fuel container less than 50 ft from multiple wellheads/not in compliance with CECMC rules  Spoke with TEP consultant about observed compliance issue & he said he would speak with the rig crew about it.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Equipment:</b>			corrective date
Type: Other	# 1		
Comment:	Rig heater		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	500 bbl frac tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Winch truck		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Tubing scanning truck		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Accumulator		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	452559	Type:	WELL	API Number:	045-23734	Status:	PR	Insp. Status:	PR
Workover									
Comment:		<div>HIT repair</div> <div>FORM 42 document # 404079226</div>							
Corrective Action:		<div></div>						Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Small amount of light compaction
		Gravel				Sparse to none in areas
		Ditches				
		Culverts				
		Compaction				Light compaction in some sections
Gravel						Sparse to none in areas

Comment: Limited Stormwater inspection due to snow & ongoing workover operations on location

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Limited inspection/audit due to ongoing workover operations on location	smelserw	02/09/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905712	Inspection/Audit 708905711 photo log	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6911357">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6911357</a>