

# Inspection Photos

Loc: 484357

Operator: DESERT EAGLE OPERATING LLC

Inspection Date: 2/10/2025

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south toward the access road and location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

## Inspection Photos



**Photo 2.** Facing southwest toward the wellsite. There is oil stained at red arrow that needs to be cleaned up.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

## Inspection Photos



**Photo 3.** Facing southwest closer to the well where drill cuttings were previously spilled. There is still white stains in this area.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

Inspection Photos



**Photo 4.** Facing at the wellhead. There is red drill cutting still present at the wellhead. Sign and fences have been reinstalled.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

## Inspection Photos



**Photo 5.** Facing northwest at the location. There are stained soils southeast of the wellhead that have not been cleaned up. Previous CA was not completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

## Inspection Photos



**Photo 6.** Facing east toward the flowline disturbance. The vegetation is not establishing along the flowline and there are vehicle tracks which a causing unnecessary disturbance. The flowline must be reclaimed and stabilized.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

## Inspection Photos



**Photo 7.** Facing northeast at the location. The wattles have been reinstalled at the south side of the location. Disturbed areas will need to be reseeded.



## Inspection Photos



**Photo 8.** Facing northeast at the location. The wattles have been reinstalled at the south side of the location. Disturbed areas will need to be reseeded. Compacted soils must be decompacted by cross ripping to at least 8 inches.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:484357 | Date: 2/10/2025

Inspection Photos



**Photo 9.** Facing east at the wellsite.

