

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SWSE

Location ID: 335421

Date: 2/10/2025



Location Overview – Photo #06552



Location – Photo #06551

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SWSE

Location ID: 335421

Date: 2/10/2025



Location – Photo #06554



Location – Photo #06555

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SWSE

Location ID: 335421

Date: 2/10/2025



Open Wellhead Cellar – Photo #06553



Insufficient Erosion Controls – Photo #06556

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, FEDERAL-66S95W/29SWSE

Location ID: 335421

Date: 2/10/2025



Insufficient Erosion Controls – Photo #06557



Insufficient Erosion Controls – Photo #06558