

Inspection Photos

Loc #: 481115

Operator: DESERT EAGLE OPERATING

Inspection Date: 2/10/2025

County: Las Animas



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. There is oil stained soil at red arrow that needs to be cleaned up.



Inspection Photos



Photo 2. The stained soil is from the leak at the track which was previously identified. Previous CA to clean up was not completed.



Inspection Photos



Photo 3. Facing southeast toward the wellsite. The wattles have been replaced.



Inspection Photos



Photo 4. The fence and well sign have been reinstalled.



Inspection Photos



Photo 5. East side of the location facing northwest. Disturbed areas of the location need to be reseeded.



Inspection Photos



Photo 6. Facing east toward the flowline disturbance. There is subsidence along the flowline that needs to be filled in.

