

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025



Feb 10, 2025 at 10:39:50 AM
+39.381793,-108.089158 ±6.19m
Parachute

Photo # 4429 Entrance to location



Feb 10, 2025 at 11:00:52 AM
+39.381290,-108.088512 ±4.93m
Parachute

Photo # 4456 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025




Photo # 4432 Location



Photo # 4438 Location




Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025



Feb 10, 2025 at 10:53:55 AM
+39.381384,-108.088728 ±4.40m
Parachute

Photo # 4447 Location



Feb 10, 2025 at 10:59:49 AM
+39.381290,-108.088512 ±4.93m
Parachute

Photo # 4454 Location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025



Photo # 4471 SE corner of location



Photo # 4472 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025



Photo # 4273 NW corner of location



Photo # 4474 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025



Photo # 4443 Failure to maintain chemical BMP/chemical containment approximately 3/4th full of fluid/not sufficient to contain possible spill



Photo # 4468 Open ended load line

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC KNOX/03-08 PAD

Location ID: 414268

Date: 02/10/2025



Photo # 4469 Open ended load line




Photo # 4460 Tank lacks required labeling/does not comply with CECMC rules