

Final Reclamation and Stormwater Inspection

Date: 02/11/2025

Operator: BAYSWATER EXPLORATION &
PRODUCTION LLC - 10261

Location ID: 302324

Inspection Document #: 718700123

Weld County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Dyer 2-25
Location ID: 302324




Photo 1. Google Earth aerial imagery (circa 04/2006) illustrating that an access road did not exist prior to the subject Well (API 123-28147) being spud on 10/24/2010.

Inspection Photos
Location Name: Dyer 2-25
Location ID: 302324



Photo 2. Google Earth aerial imagery (circa 07/2011) illustrating that an access road appears to have been constructed in connection to the subject Well (API 123-28147).

Cardinal Photos

Site Investigation and Photos Date

05 Sep 2024

Cardinal directional photos of the site.



Photo 3. Screenshot from Page 8 of the drone closure report (doc #404067592). No other documentation within the drone closure report illustrates the northern, or start, of the access road, which does not appear to have been reclaimed.

Inspection Photos
Location Name: Dyer 2-25
Location ID: 302324



Photo 4. Google Maps imagery (circa 10/2009) illustrating that the access road entrance did not exist prior to oil and gas development.

Inspection Photos
Location Name: Dyer 2-25
Location ID: 302324



Photo 5. Google Maps imagery (circa 08/2023) illustrating that the access road remains and does not appear to have been reclaimed.