

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2025

Submitted Date:

02/06/2025

Document Number:

713400684**FIELD INSPECTION FORM**Loc ID 322450 Inspector Name: Popejoy, Dusty On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10770Name of Operator: VISION ENERGY LLCAddress: P O BOX 370City: IGNACIO State: CO Zip: 81137**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, DNR		dnr_cogccengineering@state.co.us	
ENERGY, VISION		pbechtolt@maralexinc.com	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
ENERGY, VISION		mrine20@maralexinc.com	
Trujillo, Aaron		aaron.trujillo@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
ENERGY, VISION		mollieo@maralexinc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210532	WELL	SI	07/06/2021	GW	045-06288	USA 1-28DF	PA

General Comment:**CECMC Inspection/Audit Report Summary**

On 2/3/2025 at approximately 13:06 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at VISION ENERGY LLC USA-67S99W/28SEW (USA 1-28DF) at Location ID #322450 in Garfield County, Colorado.

Please refer to document numbers 402705092 & 402773585 appears the well has been P&A.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

During the inspection/audit, the following compliance issues were observed:

1. Equipment - Equipment on location is not in compliance with CECMC reclamation rules with a CA of 03/6/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective ActionL		Date:	

Overall Good: ☐

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris west side of lease road, refer to photos		
Corrective Action:			Date:

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Other	# 6		
Comment:	Equipment on location is not in compliance with CECMC reclamation rules, refer to photos		
Corrective Action:	Comply with CECMC reclamation rules		Date: 03/06/2025

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	210532	Type:	WELL	API Number:	045-06288	Status:	SI	Insp. Status:	PA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
<u>Comment:</u> Please refer to document numbers 402705092 & 402773585 appears the well has been P&A. Unable to locate FORM 6 Subsequent Report of Abandonment.									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Compaction						Light compaction
		Ditches				
		Compaction				Light compaction

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Equipment for corrective action and Inspected Facilities & Housekeeping for comments.	popejoyd	02/06/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404084148	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6908124
713400685	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6908118