

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11NWN (GM 31-11 PAD)

Location ID: 334982

Date: 02/11/2025



Photo # 4764 Entrance to location




Photo # 4780 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11NWN (GM 31-11 PAD)

Location ID: 334982

Date: 02/11/2025



Feb 11, 2025 at 1:10:34 PM  
+39.458264,-108.075114 ±3.35m  
De Beque

Photo # 4765 Location



Feb 11, 2025 at 1:16:39 PM  
+39.458070,-108.075228 ±4.07m  
De Beque

Photo # 4776 Location



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11NWN (GM 31-11 PAD)

Location ID: 334982

Date: 02/11/2025



Photo # 4779 Location



Photo #4788 SE corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11NWN (GM 31-11 PAD)

Location ID: 334982

Date: 02/11/2025



Photo # 4789 SW corner of location



Photo # 4790 NW corner of location



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11NWN (GM 31-11 PAD)

Location ID: 334982

Date: 02/11/2025



Photo # 4791 NE corner of location



Photo # 4787 Open ended load line



## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11NWN (GM 31-11 PAD)

Location ID: 334982

Date: 02/11/2025



Photo # 4778 Lacks required labeling/does not comply with CECMC rules



Photo # 4794 Rill erosion on access road, south side of location