

Inspection Photos

February 12th, 2024

Operator: Williford Resources - 96735

Location ID: 325692

Inspection Document #: 714001826

La Plata County, CO

Township: SENE 23 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Macey 1
Location ID: 325692

2/12/25
84° E



Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06842

Inspection Photos
Location Name: Macey 1
Location ID: 325692



Photo 2. View of wellhead/pump jack, no stained soil was observed.

Inspection Photos
Location Name: Macey 1
Location ID: 325692

2/12/25
116° SE



Photo 2. View of tank battery.



Inspection Photos
Location Name: Macey 1
Location ID: 325692

2/12/25
260° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Interim reclamation area composed of Rabbitbrush, Broom Snakeweed and Sagebrush.

API #: 067-06842

Inspection Photos
Location Name: Macey 1
Location ID: 325692

2/12/25
13° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Rabbitbrush, Broom Snakeweed and James Galleta.

API #: 067-06842