

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/05/2025

Submitted Date:

02/08/2025

Document Number:

708905702**FIELD INSPECTION FORM**Loc ID 334858 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
QB Energy		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211514	WELL	SI	09/01/2024	GW	045-07274	KRK 7-15 (07E)	SI
260074	WELL	PR	02/01/2008	GW	045-07820	PITMAN 18-2A (07E)	PR
260075	WELL	PR	02/16/2006	GW	045-07821	PITMAN 18-1A (07E)	PR

General Comment:[CECMC Inspection/Audit Report Summary](#)

On 02/05/2025 at approximately 12:36 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at QB Energy KRK 7-15 (07E)

Location # 334858 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Equipment - Rupture disc vent line does not comply with CECMC pressure safety device rules with a CA date of 02/15/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Multi Lease pad - Shared facilities with KRK 7-11A location # 334894 & KRK 7-10A location # 333170

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Signs at separators		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign near entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	1 battery lacks required signage/not in compliance with CECMC rules 1 well is missing on battery that does have signage/not in compliance with CECMC rules		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/>	Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 3		

Comment:	Pressure transducers located on bradenheads, bradenhead valves are accessible.			Date:	
Corrective Action:				Date:	
Type: Pig Station	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Bird Protectors	# 3				
Comment:				Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 2				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 2				
Comment:	PITMAN 18-1A not on plunger lift Remaining 2 wells on plunger lift			Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 1				
Comment:	Summit Midstream			Date:	
Corrective Action:				Date:	
Type: Vertical Heated Separator	# 5				
Comment:				Date:	
Corrective Action:				Date:	
Type: Other	# 1				
Comment:	Rupture disc vent line does not comply with CECMC pressure safety device rules			Date:	
Corrective Action:	Comply with CECMC pressure safety device rules			Date:	02/15/2025
Type: Gas Meter Run	# 7				
Comment:				Date:	
Corrective Action:				Date:	
Type: Deadman # & Marked	# 7				
Comment:	6 marked deadman 1 improperly marked deadman - please refer to photo log All guy line anchors left buried for future use will be identified by a marker of bright color not less than 4 feet in height and not greater than 1 foot east of the guy line anchor			Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Centralized containment Unlined containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Centralized containment with 1000 gal methanol tank Unlined containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:	Tanks equipped with telemetry				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Separate centralized containment Unlined containment			
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	211514	Type:	WELL	API Number:	045-07274	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder:									
Comment: Shut In Last produced August 2024									
Corrective Action: Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	260074	Type:	WELL	API Number:	045-07820	Status:	PR	Insp. Status:	PR
Producing Well									
Comment: Producing, well on plunger lift									
Corrective Action: Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	260075	Type:	WELL	API Number:	045-07821	Status:	PR	Insp. Status:	PR
Producing Well									
Comment: Producing, well not on plunger lift									
Corrective Action: Date:									
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
		Compaction				
		Gravel				
Gravel						Sparse to none in areas
		Culverts				
Compaction						Light compaction in some areas
Berms						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Equipment for corrective action & also refer to Signs/Marker & Equipment for comments.	smelserw	02/08/2025
Multi Lease pad - Shared facilities with KRK 7-11A location # 334894 & KRK 7-10A location # 333170		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404086944	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6910994
708905703	Inspection/Audit 708905702 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6910992
708905704	Inspection/Audit 708905702 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6910993