

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 4448 From entrance to location



Photo # 4449 From entrance to location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021




Photo # 4450 Location



Photo # 4451 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 4452 Location



Photo # 4453 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Feb 10, 2025 at 11:04:46 AM
CO



Feb 10, 2025 at 11:09:29 AM
CO

Photo # 4454 Location

Photo # 4455 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 4456 Location



Photo # 4457 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 4458 Staining near separator



Photo # 4459 Damaged hose/debris

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC SNYDER C Pad

Location ID: 336021



Photo # 4460 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 4461 Cellar lacks wildlife egress