

Inspection Photos

API: 011-06083

Operator: RENEGADE OIL & GAS COMPANY

Inspection Date: 2/14/2025

County: BENT



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast along the access road. There is erosion along the road that must be repaired and stabilized. Vehicles are driving off the original road causing more disturbance.



Inspection Photos



Photo 2. Facing southeast along the access road. There is erosion along the road that must be repaired and stabilized. Red arrow points to 4.5' shovel for scale. Vehicles are driving outside of the original access road to avoid the eroded road.



Inspection Photos



Photo 3. Facing southeast toward the wellsite and tank battery.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Stained soil have faded but still remain at the base of the tank.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 5. Facing east at the location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing north toward the well which is temporarily abandoned. Unused equipment needs to be removed.



Inspection Photos



Photo 7. Facing north toward the TA'd well. The pumpjack and parts are unused equipment that need to be removed.



Inspection Photos



Photo 8. Well sign is posted at the meter shed. Emergency number is disconnected.

