

# Inspection Photos

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325385

Inspection Document #: 714001844

La Plata County, CO

Township: SWNW 20 34N 6W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Smith 01-20 1  
Location ID: 325385

2/13/25  
150° SE



**Photo 1.** View of the well pad taken from the access point facing center.

Inspection Photos  
Location Name: Smith 01-20 1  
Location ID: 325385

2/13/25  
85° E



**Photo 2.** Stained soils at pump jack muffler.



Inspection Photos  
Location Name: Smith 01-20 1  
Location ID: 325385

2/13/25  
350° N



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 3.** Labels at produced water tanks are starting to deteriorate, future maintenance is advised.

API #: 067-06285

Inspection Photos  
Location Name: Smith 01-20 1  
Location ID: 325385



**Photo 4.** View of stormwater issues at access point culvert. Width of gully erosion has increased since previous inspection, head cut forming at culvert entrance. Additional stabilization measures/stormwater BMPs are needed.



**Photo 5.** Portions of the cut slope and seeding efforts appear successful, portion of the cutslope remains with bare soils.

Inspection Photos  
Location Name: Smith 01-20 1  
Location ID: 325385



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 6.** Reference area composed of Juniper, Sagebrush and Grama.

API #: 067-06285