

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/10/2025

Submitted Date:

02/18/2025

Document Number:

707603667**FIELD INSPECTION FORM**Loc ID 438901 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
438898	WELL	PR	08/01/2019	OW	123-40195	North Platte Federal 11-14-22HNC	PR
438899	WELL	PR	05/01/2022	OW	123-40196	North Platte Federal A11-E14-22HNB	PR
438900	WELL	PR	07/31/2015	OW	123-40197	North Platte Federal A-E-22HC	PR
438902	WELL	PR	08/14/2015	OW	123-40198	North Platte Federal F-J-22HNC	PR
438903	WELL	PR	07/23/2015	OW	123-40199	North Platte Federal F11-J14-22HNB	PR
438904	WELL	PR	08/23/2015	OW	123-40200	North Platte Federal F21-J24-22HNB	PR

General Comment:

This is a WELL inspection.
Well(s): 6: Producing | PR.
Battery: Active.

Centralized Battery serves 2 Location IDs
(433629, 438901).
(Well(s): 12: Producing | PR; 1: Shut-In| SI).

Centralized Battery serves 1 Tank Battery Facility ID
(487917).

Reference (Associated Well(s), Battery / Facility Inspections):
A.) Field Inspection Report doc. #707603665 and/or Location ID #433629 for PR, SI Well(s) info.
B.) Field Inspection Report doc. #707603667 and/or Location ID #438901 for PR Well(s) info.
C.) Field Inspection Report doc. #707603669 and/or Facility ID #487917 for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wellsite(s): 6		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wellsite(s): 6 Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 6		
Comment:	Wellsite(s): 7 Gas lift injection lines.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:	Wellsite(s): 6: Gas Lift Allocation; (Civitas). Calibration card(s) indicates calibration <= 1 year. Last calibration: 08/13/2024.		
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Wellsite(s): 6 Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:	Wellsite(s): 6		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.391527,-104.422185	
Comment:	Centralized Battery serves 2 Location IDs (433629, 438901). (Well(s): 12: Producing PR; 1: Shut-In SI). Centralized Battery serves 1 Tank Battery Facility ID (487917).					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities			
Facility ID: 438898	Type: WELL	API Number: 123-40195	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 04/18/2024	Annual Brhd Completed? Yes		
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 438899	Type: WELL	API Number: 123-40196	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 05/18/2024	Annual Brhd Completed? Yes		
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 438900	Type: WELL	API Number: 123-40197	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	
BradenHead			
Date of Last Brhd Test: 04/18/2024	Annual Brhd Completed? Yes		
Last Brhd Test Results	Initial Surf Csg Pressure: 0	Fluid Type:	
	End Surf Csg Pressure: 0		
Comment:			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 438902	Type: WELL	API Number: 123-40198	Status: PR Insp. Status: PR
Producing Well			
Comment: Producing PR.			
Corrective Action:		Date:	

BradenHead			
Date of Last Brhd Test: 05/18/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438903	Type: WELL	API Number: 123-40199	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: Producing PR.	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 05/18/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 438904	Type: WELL	API Number: 123-40200	Status: PR	Insp. Status: PR
---------------------	------------	-----------------------	------------	------------------

Producing Well	
Comment: Producing PR.	
Corrective Action:	Date:

BradenHead			
Date of Last Brhd Test: 05/18/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0	Fluid Type:
		End Surf Csg Pressure: 0	
Comment:			
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>CECMC Inspection Report Synopsis:</p> <p>On MON 02/10/2025 at approximately 14:22 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte/F-22 Location ID: 438901 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm.</p> <p>While there, I observed: Well(s): 6: Producing PR. Battery: Active.</p> <p>Routine inspection.</p> <p>*Any Corrective Actions from prior inspections that have not been addressed remain applicable.</p>	evinsb	02/18/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603668	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6925064