

Inspection Photos  
Location Name: Carl A Miller B #13  
Location ID: 318668



Photo 1: Wellhead Sign



Photo 2: SI pumpjack



Inspection Photos  
Location Name: Carl A Miller B #13  
Location ID: 318668



Photo 3: Possible leak, mechanical issue



Photo 4: Possible leak, mechanical issue



# Inspection Photos

## Location Name: Carl A Miller B #13

### Location ID: 318668



Photo 5: Tank Battery Sign



Photo 6: Centralized tank battery