

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/19/2025

Submitted Date:

02/19/2025

Document Number:

717701137

**FIELD INSPECTION FORM**

Loc ID 475652 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1700 LINCOLN ST STE 4550  
City: DENVER State: CO Zip: 80203

**Findings:**

7 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
475653	OFF-LOCATION FLOWLINE	AC	01/09/2023		-	Carl A Miller Sub Battery	AC

**General Comment:**

[This is a routine audit of the tank battery](#)  
[Snow Covered Ground](#)

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<a href="#">Adequate</a>		Date: _____
Corrective Action:			

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	<a href="#">The Gas Meter Run appeared to be out of calibration. The Gas Meter Run appears to be showing flow rates and volumes.</a>		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Other	#		
Comment:	<a href="#">Header for well flow lines</a>		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.075223,-104.910408
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

<b>Paint</b>	
Condition	
Other (Content)	
Other (Capacity)	50 BBLs
Other (Type)	

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
123-07704
123-08702
123-12831
123-07579
123-08978
123-08979
123-09655
123-08970
123-07681
123-07597
123-09051
123-15954
123-07713
123-07602

**AirsID**

API Number	AirsID
------------	--------

123-08971

123-07428

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 475653 Type: OFF- API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p><a href="#">ECMC Inspection Report Summary</a></p> <p>On Wednesday, February 19, 2025, at approximately 9:49 AM, Inspector Adam Burns conducted an on-site inspection at the following location:</p> <p>Tank Battery: Carl A Miller Sub Battery                      Operator: KP Kauffman Company INC                      Facility #475653                      County: Weld                      Weather: Cold and Snow Covered Ground                      During the inspection, the tank battery appeared to have open valves on the separator. The Gas Meter Run appeared to be out of calibration. The Gas Meter Run appears to be showing flow rates and volumes.</p>	burnsa	02/19/2025

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717701138	Annotation Report	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6926633">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6926633</a>
717701139	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6926634">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6926634</a>