

Inspection Photos

Location Name: COCKROFT USX A-66N64W/11NWNE

Location #: 306461



Photo #1

Cockroft USX A 11-2 (123-24709) Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf



Photo #2

Cockroft USX A 11-2 Wellsite

Plugged & Abandoned | PA

Plugging Ops; Cementing: cmt-surf

Site safety signage



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources


Inspection Photos

Location Name: COCKROFT USX A-66N64W/11NWNE
Location #: 306461



Colorado Energy & Carbon Management Commission
Weld County
+40.507803,-104.517195
106° E
2025-02-18 11:56

Photo #3
Cockroft USX A 11-2 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
Wellsite entrance



Colorado Energy & Carbon Management Commission
Weld County
+40.507086,-104.514501
165° S
2025-02-18 11:47

Photo #4
Cockroft USX A 11-2 Wellsite
Plugged & Abandoned | PA
Plugging Ops; Cementing: cmt-surf
JSA: 2025-02-18

