


**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Debris



Oily waste and staining around tanks

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Staining around tanks




Staining around tanks

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**




Blow down line to tank missing back pressure valve



Tank venting to atmosphere

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Tank missing pressure relief valve



Location from South entrance

**Antler Energy LLC
Baggs Land & Cattle 1
Location ID: 312868**



Location from Northeast corner



Location from Northwest corner