

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
403981475

Date Received:  
02/20/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302850  
Inspection Date: 10/03/2024 FIR Submit Date: 10/03/2024 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334896

Location Name: GM Number: 34-4 County: \_\_\_\_\_  
Qtrqtr: SWSE Sec: 4 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.461755 Longitude: -108.110108

FACILITY - API Number: 05-045-00 Facility ID: 334896

Facility Name: GM Number: 34-4  
Qtrqtr: SWSE Sec: 4 Twp: 7S Range: 96W Meridian: 6  
Latitude: 39.461755 Longitude: -108.110108

CORRECTIVE ACTIONS:

**1** CA# 199294

Corrective Action: Secure equipment to comply with Rule 608.e. Date: 10/08/2024

Response: CA COMPLETED Date of Completion: 10/17/2024

Operator Comment: Loadline and vent line on tank have been plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 199295

Corrective Action: Secure equipment to comply with Rule 608.e.

Date: 10/08/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Load line on tanks have been plugged. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**3** CA# 199296

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Location and access road have been bladed/graded to remove rills and increase stabilization. Ditches have been pulled and reconstructed for better water conveyance. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #199294: Loadline and vent line on tank have been plugged. Corrective Action complete.  
CA #199295: Load line on tanks have been plugged. Corrective Action complete.  
CA #199296: Location and access road have been bladed/graded to remove rills and increase stabilization. Ditches have been pulled and reconstructed for better water conveyance. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 2/20/2025 12:01:37 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

Document Number	Description

Total Attach: 0 Files