

Inspection Photos
Location Name: Carl A Miller B #13
Location ID: 318668



Photo 1: Wellhead Sign



Photo 2: Repair

Inspection Photos
Location Name: Carl A Miller B #13
Location ID: 318668



Photo 3: Repair

Photo 4: Tank Battery sign

Inspection Photos
Location Name: Carl A Miller B #13
Location ID: 318668



Photo 5: Centralized tank battery