

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7525 From entrance to location



Photo # 7526 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Feb 19, 2025 at 2:05:56 PM
CO

Photo # 7527 Location



Feb 19, 2025 at 2:01:29 PM
CO

Photo # 7528 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7529 Location



Photo # 7530 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7531 Location



Photo # 7532 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7533 Location



Photo # 7534 Staining near separator

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703




Photo # 7535 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 7536 Rupture disc & PRV vent lines do not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7537 Rupture disc vent line does not comply with CECMC pressure safety device rules



Photo # 7538 Battery sign lacks required information

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7539 Tank label missing required information



Photo # 7540 Tank label faded & some required information is illegible



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad

Location ID: 334703



Photo # 7541 Debris/wildlife hazard



Photo # 7542 Debris/wildlife hazard