

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2025

Submitted Date:

02/21/2025

Document Number:

708905799**FIELD INSPECTION FORM**Loc ID 334703 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: 1058 COUNTY ROAD 215City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**37 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286059	WELL	PR	10/01/2024	GW	045-12610	CIRCLE B LAND 21A-35-692	PR
286060	WELL	PR	02/10/2007	GW	045-12609	CIRCLE B LAND 21C-35-692	PR
286061	WELL	PR	02/20/2007	GW	045-12608	CIRCLE B LAND 32C-35-692	PR
286062	WELL	PR	12/10/2008	GW	045-12607	CIRCLE B LAND 31C-35-692	PR
286063	WELL	PR	02/14/2007	GW	045-12606	CIRCLE B LAND 31A-35-692	PR
286064	WELL	PR	02/24/2007	GW	045-12605	CIRCLE B LAND 22C-35-692	PR

General Comment:

CECMC Inspection/Audit Report Summary

On 02/19/2025 at approximately 14:01 hours, I, Compliance Specialist, Wayne Smelser

Conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 21A-35-692 Pad.

Location # 334703 in Garfield County Colorado.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection/audit the following compliance issues were observed:

1. Signs/Marker - Battery sign lacks required information with a CA date of 03/23/2025
2. Signs/Marker - Tank labels missing required information with a CA date of 03/23/2025
3. Housekeeping - Debris on location with a CA date of 02/28/2025
4. Equipment - Rupture disc & PRV vent lines do not comply with CECMC pressure safety device rules with a CA date of 02/28/2025

A follow up on this site inspection/audit needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection/audit report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign on gate at start of lease road		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	1 Tank label missing required information 1 Tank label faded & some required information is illegible 3-4 other labels are weathered/damaged & some required info is starting to become illegible		
Corrective Action:	All Tanks with a capacity of 10 Barrels or greater will be labeled or posted with the following information: A. Name of Operator B. Operator's emergency contact telephone number C. Tank capacity D. Tank contents and E. NFPA label or equivalent globally harmonized label	Date:	03/23/2025
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign lacks required information		
Corrective Action:	The Tank battery sign will be no less than 3 square feet and no more than 6 square feet, and will provide: A. Name of the Operator B. Telephone number at which the Operator can be reached at all times C. Telephone number for local emergency services (911 where available) D. The public road used to access the Tank battery site E. Well name(s) and API number(s) associated with the Tank battery and the legal location of the Well(s) and F. Location, including the quarter/quarter section, of the Tank battery.	Date:	03/23/2025
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911/970-285-9377		

Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Small amount of staining near separator - please refer to photo log		
Corrective Action:			Date:
Type	DEBRIS		
Comment:	Debris on location, some of the debris also constitutes a wildlife hazard		
Corrective Action:	Comply with CECMC rules regarding debris & CECMC wildlife rules		Date: 02/28/2025
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	1 tank battery hog panels 2 tank batteries cattle panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Cattle panels		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:			Date:
Type	OTHER		
Comment:	Chemical tank - cattle panels		
Corrective Action:			Date:
Equipment:			
Type: Emission Control Device	# 1	corrective date	
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:	All wells on plunger lift		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Liquid nitrogen tank Unable to locate FORM 4 SUNDRY for equipment/not in compliance with CECMC rules If operator remains out of compliance corrective action may be issued in future inspections		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 6		
Comment:	Taylor plugs located on bradenheads, bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	3 rupture disc vent lines & 1 PRV vent line do not comply with CECMC pressure safety device rules		
Corrective Action:	Comply with CECMC pressure safety device rules	Date:	02/28/2025
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth					
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)	Unknown - some info illegible	
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Seperate containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	500 gal	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	In containment with the 200 bbl tank that contents are unknown			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth				
Comment:	Centralized containment			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
GLYCOL	1	200 BBLS	STEEL AST		,
Comment:					

Corrective Action:						Date:	
<u>Paint</u>							
Condition		Adequate					
Other (Content)		Used Glycol					
Other (Capacity)							
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth							
Comment: Seperate containment							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	OTHER	STEEL AST		,		
Comment:							
Corrective Action:		Date:					
<u>Paint</u>							
Condition		Adequate					
Other (Content)							
Other (Capacity)		250 bbl					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth							
Comment: Centralized containment							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	4	OTHER	HEATED STEEL AST		,		
Comment:							
Corrective Action:		Date:					
<u>Paint</u>							
Condition		Adequate					
Other (Content)							
Other (Capacity)		250 bbl					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth							
Comment: Centralized containment							
Corrective Action:						Date:	
<u>Venting:</u>							

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 286059 Type: WELL API Number: 045-12610 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286060 Type: WELL API Number: 045-12609 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286061 Type: WELL API Number: 045-12608 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286062 Type: WELL API Number: 045-12607 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286063 Type: WELL API Number: 045-12606 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 286064 Type: WELL API Number: 045-12605 Status: PR Insp. Status: PR

Producing Well

Comment: Producing, well on plunger lift

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Compaction						Small amount of light compaction
Gravel						Sparse to none in areas
		Ditches				
Waddles						
		Compaction				Small amount of light compaction
		Gravel				Sparse to none in areas
				Material Handling And Spill Prevention		Chemical tank containment

Comment: [Limited Stormwater inspection due to snow](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Please refer to Signs/Marker, Housekeeping & Equipment for corrective actions	smelserw	02/21/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708905800	Inspection/Audit 708905799 photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6930297
708905801	Inspection/Audit 708905799 Stormwater photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6930298