

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7191 From entrance to location

Photo # 7192 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7193 Location



Photo # 7194 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7195 Location



Photo # 7196 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7197 Location



Photo # 7198 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7199 Unused equipment



Photo # 7200 Unused equipment

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7201 Tank capacity incorrect




Photo # 7202 Tank capacity

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7203 Wellhead sign weathered/faded & required info is becoming illegible



Photo # 7204 Wellhead sign weathered/faded & required info is becoming illegible

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7205 Dead bird observed in tank battery



Photo # 7206 Dead bird observed in tank battery

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 23B-35-692 Pad

Location ID: 334629



Photo # 7207 PRV vent line does not comply with CECMC pressure safety device rules & general safety rules



Photo # 7208 Debris