

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5152 Entrance to location



Photo # 5188 Location

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5153 Location



Photo # 5173 Location

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5184 Location



Photo # 5185 Location

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5194 NW corner of location



Photo # 5195 SW corner of location

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5196 SE corner of location



Photo # 5197 NE corner of location

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5156 Open hole with no wildlife egress/wildlife hazard



Photo # 5169 Open hole with no wildlife egress/wildlife hazard

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5176 Open hole with no wildlife egress/wildlife hazard



Photo # 5181 Open hole with no wildlife egress/wildlife hazard

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5188 Some info is starting to become illegible



Photo # 5189 Tank labels contain inaccurate contact info and some info is starting to become illegible/not in compliance with CECMC rules

Inspection/Audit Photos

Location: QB Energy HYRUP-68S96W/2NWSE (PAD-2 J)

Location ID: 334158

Date: 2/18/2025



Photo # 5190 Tank labels contain inaccurate contact info and some info is starting to become illegible/not in compliance with CECMC rules



Photo # 5168 Debris