

Inspection Photos  
Location: PCW 41-33  
Location ID: 307307  
API # 05-071-06204



Photo 1 –Well placard



Photo 2 – Wellhead

**Inspection Photos**  
**Location: PCW 41-33**  
**Location ID: 307307**  
**API # 05-071-06204**



**Photo 3 – Meter House**



**Photo 4 – Wellhead, white stained  
soils are present.**

**Inspection Photos**  
**Location: PCW 41-33**  
**Location ID: 307307**  
**API # 05-071-06204**



**Photo 5 – Source area, area impacted by spill**



**Photo 6 – Area impacted by spill**

**Inspection Photos**  
**Location: PCW 41-33**  
**Location ID: 307307**  
**API # 05-071-06204**




**Photo 7 – Source area**



**Photo 8 – Equipment, source of leak**

**Inspection Photos**  
**Location: PCW 41-33**  
**Location ID: 307307**  
**API # 05-071-06204**



**Photo 9 – Area impacted by spill**

**Photo 10 – Spill Path**

**Inspection Photos**  
**Location: PCW 41-33**  
**Location ID: 307307**  
**API # 05-071-06204**



**Photo 11 – Spill Path**



**Photo 12 – Spill Path leading to culvert**

**Inspection Photos**  
**Location: PCW 41-33**  
**Location ID: 307307**  
**API # 05-071-06204**



**Photo 13 – Culvert in road, direction change**

**Photo 14 – Pool at end of culvert**