

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Feb 18, 2025 at 12:40:46 PM
+39.372810,-108.073392 ±6.91m
Parachute

Photo # 5208 Entrance to location



Feb 18, 2025 at 1:14:11 PM
+39.373080,-108.072409 ±3.43m
Parachute

Photo # 5243 Location/Well 2-34A info is missing

Inspection/Audit Photos
Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)
Location ID: 334103
Date: 02/18/2025



Photo # 5244 Location/Well 2-34A info is missing



Photo # 5209 Location

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Feb 18, 2025 at 12:53:50 PM
+39.372884,-108.073044 ±6.34m
Parachute

Photo # 5218 Location



Feb 18, 2025 at 1:02:18 PM
+39.373175,-108.072801 ±4.75m
Parachute

Photo # 5228 Location

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Photo # 5242 Location



Photo # 5256 Location

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Photo # 5257 SE corner of location



Photo # 5258 NE corner of location

Inspection/Audit Photos
Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)
Location ID: 334103
Date: 02/18/2025



Photo # 5259 NW corner of location



Photo # 5260 SW corner of location

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Photo # 5213 Open hole with no wildlife egress/wildlife hazard



Photo # 5223 Open hole with no wildlife egress/wildlife hazard

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Photo # 5236 Open hole with no wildlife egress/wildlife hazard



Photo # 5237 Open hole with no wildlife egress/wildlife hazard

Inspection/Audit Photos

Location: QB ENERGY HYRUP/2-34B (PAD - 2 0)

Location ID: 334103

Date: 02/18/2025



Photo # 5238 Open hole with no wildlife egress/wildlife hazard



Photo # 5227 Debris