

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2025

Submitted Date:

02/24/2025

Document Number:

715800731**FIELD INSPECTION FORM**

Loc ID 336452 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**17 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243657	WELL	PR	07/01/2017	OW	123-11449	FREDERICK UNIT A 1	PR
243673	WELL	PR	03/17/1984	GW	123-11465	FREDERICK UNIT 'B' 1	PR
243972	WELL	PR	07/01/2017	OW	123-11764	FREDERICK UNIT C 1	PR
243973	WELL	PR	08/01/2023	OW	123-11765	FREDERICK UNIT D 1	PR

**General Comment:**

[This is a wellsite scout card audit followed by a field inspection.](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type			
Comment:	dead vegetation needs to be addressed		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:	hog fence x 4		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Chain link topped with barb wire, needs to be addressed in several areas		
Corrective Action:		Date:	

**Equipment:**

Type: Prime Mover	# 4		corrective date
Comment:	electric motors		
Corrective Action:		Date:	
Type: Pump Jack	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	electric panels are on.		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities			
Facility ID: 243657	Type: WELL	API Number: 123-11449	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 09/03/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0      Fluid Type:	
End Surf Csg Pressure: 0			
Comment: Plumbed to surface			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 243673	Type: WELL	API Number: 123-11465	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 10/14/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0      Fluid Type:	
End Surf Csg Pressure: 0			
Comment: Plumbed to surface			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 243972	Type: WELL	API Number: 123-11764	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	
<b>BradenHead</b>			
Date of Last Brhd Test: 10/10/2024		Annual Brhd Completed? Yes	
Last Brhd Test Results		Initial Surf Csg Pressure: 0      Fluid Type:	
End Surf Csg Pressure: 0			
Comment: Plumbed to surface			
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID: 243973	Type: WELL	API Number: 123-11765	Status: PR      Insp. Status: PR
<b>Producing Well</b>			
Comment: PR			
Corrective Action:		Date:	

BradenHead	
Date of Last Brhd Test:	01/20/2025
Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure: 0
	Fluid Type:
	End Surf Csg Pressure: 0
Comment:	plumbed to surface
Corrective Action:	
	Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>This is a follow up wellsite inspection to FIR #714201658.</p> <p>The following CA have been addressed:</p> <p>605 signs have been corrected.</p> <p>606 dead vegetation still needs to be addressed.</p> <p>603 h fencing still needs to be addressed.</p> <p>Any corrective actions from previous Inspections that have not been addressed are still applicable</p> <p>Weather: Cloudy &amp; windy</p> <p>Temperature: 41*</p> <p>Location: Dry.</p>	revasr	02/24/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800732	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6932251">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6932251</a>