

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8792 From entrance to location



Photo # 8793 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8794 Location



Photo # 8795 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8796 Location



Photo # 8797 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8798 Location




Photo # 8799 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8800 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar near casing valve (HANGS A2 wellhead)



Photo # 8801 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar near casing valve (HANGS A2 wellhead)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8802 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar near casing valve (HANGS A2 wellhead)



Photo # 8803 Mechanical Condition - Possible wellhead leak /gas bubbling up through water in cellar near casing valve (HANGS A2 wellhead)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8804 Mechanical Condition - Possible leak/gas bubbling up through water in cellar near bradenhead line (HANGS A2 well)



Photo # 8805 Mechanical Condition - Possible leak/gas bubbling up through water in cellar near bradenhead line (HANGS A2 well)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Feb 24, 2025 at 3:55:23 PM
CO

Photo # 8806 Mechanical Condition - Possible leak/gas bubbling up through water in cellar near bradenhead line (HANGS A2 well)



Feb 24, 2025 at 3:55:38 PM
CO

Photo # 8807 Mechanical Condition - Possible leak/gas bubbling up through water in cellar near bradenhead line (HANGS A2 well)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8808 Staining



Photo # 8809 Same area of staining from a different angle

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS A Pad

Location ID: 336023



Photo # 8810 Cellar not properly covered/wildlife & personnel hazard