

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/24/2025

Submitted Date:

02/25/2025

Document Number:

713400752

FIELD INSPECTION FORM

Loc ID 335603 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 42 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, TEP		COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284787	WELL	PR	06/01/2017	GW	045-12271	CHEVRON TR 31-21-597	PR
284789	WELL	PR	10/10/2017	GW	045-12269	Chevron TR 32-21-597	PR
421306	WELL	PR	10/10/2017	GW	045-20351	Chevron TR 441-21-597	PR
421310	WELL	PR	10/12/2017	GW	045-20352	Chevron TR 531-21-597	PR
421314	WELL	PR	10/13/2017	GW	045-20353	Chevron TR 42-21-597	PR
421317	WELL	PR	10/12/2017	GW	045-20355	Chevron TR 432-21-597	PR
421318	WELL	PR	10/10/2017	GW	045-20356	Chevron TR 442-21-597	PR
421321	WELL	PR	10/12/2017	GW	045-20357	Chevron TR 632-21-597	PR
421322	WELL	PR	10/10/2017	GW	045-20358	Chevron TR 532-21-597	PR
421323	WELL	PR	10/10/2017	GW	045-20359	Chevron TR 342-21-597	PR

General Comment:

CECMC Inspection/Audit Report Summary

On 2/24/2025 at approximately 14:17 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at TEP ROCKY MOUNTAIN LLC Chevron/TR 32-21-597 PAD at Location ID #335603 in Garfield County, Colorado.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area & Greater Sage Grouse General Habitat Management Area.

During the inspection/audit, the following compliance issues were observed:

1. Stormwater - Failure to maintain chemical BMP's/chemical containments full of fluid & not sufficient to contain possible spill with a CA date of 02/25/2025
2. Equipment - PRV vent lines on tank heaters do not comply with CECMC pressure safety device rules with a CA date of 03/3/2025
3. Equipment - Open ended piping on chemical pumps containments/wildlife hazard/available for entry by wildlife with a CA date of 03/3/2025
4. Equipment - Open ended load lines with a CA date of 03/3/2025

A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

Location

Lease Road:			
Type	Access		
comment:	Access		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass on the side of the unit indicates that the storage tank contains an unknown fluid. No form of labeling or markers is present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	970-285-9377/911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	1 unused hose		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	OTHER		
Comment:	Chemical tanks - Hog panels		

Corrective Action:		Date:
Type	OTHER	
Comment:	Charge pump house - Hog panels	
Corrective Action:		Date:
Type	OTHER	
Comment:	Thermoelectric generator - Hog panels	
Corrective Action:		Date:
Type	IGNITOR/COMBUSTOR	
Comment:	Hog panels	
Corrective Action:		Date:
Type	SEPARATOR	
Comment:	Hog panels	
Corrective Action:		Date:
Type	TANK BATTERY	
Comment:	Hog panels	
Corrective Action:		Date:
Type	WELLHEAD	
Comment:	Hog panels	
Corrective Action:		Date:
Type	OTHER	
Comment:	Nitrogen tank - Hog panels	
Corrective Action:		Date:

Equipment:		corrective date
Type: Plunger Lift	# 10	
Comment:	All wells on plunger lift	
Corrective Action:		Date:
Type: Ancillary equipment	# 2	
Comment:	Thermoelectric generator	
Corrective Action:		Date:
Type: Bradenhead	# 10	
Comment:	TR 442-21-597 & TR 32-21-597 wells have no form of pressure monitoring equipment. Bradenhead valves are accessible. All other Bradenhead valves are accessible with telemetry for monitoring	
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	Charge Pump	
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Other	# 2	

Comment:		PRV vent lines on tank heaters do not comply with CECMC pressure safety device rules, refer to photos		Date:	
Corrective Action:		Comply with CECMC pressure safety device rules		Date:	03/03/2025
Type: Ancillary equipment	# 1				
Comment:		Cata Flow heater			
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		Nitrogen tank			
Corrective Action:				Date:	
Type: Ancillary equipment	# 1				
Comment:		Flameless gas infrared catalytic heater			
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 10				
Comment:					
Corrective Action:				Date:	
Type: Bird Protectors	# 13				
Comment:					
Corrective Action:				Date:	
Type: Other	# 8				
Comment:		Open ended load lines, refer to photos			
Corrective Action:		All load lines will be capped or plugged		Date:	03/03/2025
Type: Horizontal Heater Treater	# 1				
Comment:					
Corrective Action:				Date:	
Type: Other	# 2				
Comment:		Open ended piping on chemical pumps containments/wildlife hazard/available for entry by wildlife, refer to photos			
Corrective Action:		Comply with CECMC wildlife rules		Date:	03/03/2025
Type: Gas Meter Run	# 10				
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment	# 3				
Comment:		Chemical tanks			
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:		Tanks equipped with telemetry			
Corrective Action:				Date:	

Paint

Condition	Inadequate
-----------	------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		

Comment:	Centralized containment
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLs	HEATED STEEL AST		,

Comment:	Tanks equipped with telemetry
Corrective Action:	Date:

Paint

Condition	Inadequate
-----------	------------

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		

Comment:	Centralized containment
Corrective Action:	Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	284787	Type:	WELL	API Number:	045-12271	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	284789	Type:	WELL	API Number:	045-12269	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421306	Type:	WELL	API Number:	045-20351	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421310	Type:	WELL	API Number:	045-20352	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421314	Type:	WELL	API Number:	045-20353	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421317	Type:	WELL	API Number:	045-20355	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421318	Type:	WELL	API Number:	045-20356	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	421321	Type:	WELL	API Number:	045-20357	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421322 Type: WELL API Number: 045-20358 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 421323 Type: WELL API Number: 045-20359 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing well on plunger lift		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
				Material Handling And Spill Prevention	Fail	Failure to maintain chemical BMP's
Ditches						
		Berms				
		Ditches				

Comment: 1. Failure to maintain chemical BMP's/chemical containments full of fluid & not sufficient to contain possible spill.

At approximatley 16:30 I spoke with Kyle Tanner with TEP to inform him I was issuing a 24 hour corrective action on observed compliance issue, he told me he would get someone to take care of it.

Corrective Action: **Comply with CECMC Storm water rules**

Date: 02/25/2025

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	284696	1433403	
	284696	1433403	

ECMC Comments

Comment	User	Date
Please refer to Stormwater & Equipment for corrective actions and Housekeeping for comments. Limited storm water inspection/audit due to snow cover.	popejoyd	02/24/2025

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713400753	Inspection-Audit Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6932635