

Inspection Photos

API: 011-05055

Loc: 321208

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 2/21/2025

County: Prowers



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 2. Facing northwest toward the GAS PROCESSING PLANT and Wellsite. There is various supplies and debris scattered throughout the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



February 21, 2025
+38.202972,-103.141351
Bent County
ECMC

Photo 3. Facing northwest at the sheds and various equipment which are in disrepair. There is chemical barrels with no containment and various debris laying on the ground.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 4. Previous inspection observed the blue barrel had leaked out oily fluid onto the ground.



Photo 5. The blue barrel was removed however the oil stained soils still remain.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6&7. There are sheds in disrepair with large bird nests. Operator will need to consult with USFS and CPW regarding time restrictions and relocation of any migratory bird nests.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 8. Facing northwest at the sheds and equipment which are in disrepair. There are cattle tracks in the snow which the debris could cause injury to the livestock.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 9. Facing southeast at the west side of the location. This shed and fence are in disrepair with supplies have fallen out of the dilapidated shed.



Inspection Photos



Photo 10. There is panels, boards, and a blue barrel laying on the ground which has leaked out fluids onto the ground.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 11. Facing northeast toward the well. The fence around the pumpjack is in disrepair and there is unused equipment stored near the well.



Inspection Photos



Photo 12. Facing southeast at the location. There are various unused equipment, wire, and debris stored on location that needs to be removed.



Inspection Photos



Photo 13. Facing northeast at the location. There is various unused equipment, supplies and tanks stored at the location that will need to be removed.



Inspection Photos



Photo 14. Facing east at the south side of the location. This open top tank remains with oily fluids and a cattle track in the snow goes right up to the tank.



Inspection Photos



Photo 15. Facing toward the open top tank which has oil condensate inside the tank with no wildlife or livestock protections. The liquids were frozen at the time of inspection. Operator ignored the previous notification and corrective action.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 16. Facing northwest at the south side of the location. There is an open top fiberglass condensate tank with no wildlife or livestock protections. There are cattle tracks all around the tank indicating that cattle could be drinking out of this tank.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 17. Facing northeast at the location. The tank at red arrow was recently installed since the 8/7/24 inspection.



Inspection Photos



Photo 18. East side of the location facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 2/21/2025

Inspection Photos



Photo 19. Drone aerial photo taken on 2/4/2025. Facing northeast toward the GAS PROCESSING PLANT and Wellsite.



Inspection Photos



Photo 20. Drone aerial photo taken on 2/4/2025. Facing southwest toward the GAS PROCESSING PLANT and Wellsite.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc: 321208 | Date: 2/21/2025