

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2025

Submitted Date:

02/25/2025

Document Number:

716300580**FIELD INSPECTION FORM**Loc ID 309027 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
D DYKE, TRACY	719-846-7898	tracy.dyke@enrllc.com	Insp. w/ca's
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
286776	WELL	TA	06/01/2012	OBW	071-08984	KEENE VALLEY 31-15	TA

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	PHOTO 6: WELL HAS BEEN CONVERTED TO A SEISMIC MOTOR WELL SO ENGINE SKID AND SOUND WALLS ARE NO LONGER IN USE OR USEFULL TO THE OPERATION.		
Corrective Action:	REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 3-4-2025.	Date:	03/04/2025
Type	TRASH		
Comment:	PHOTO 4: INSULATION FROM SOUND WALLS HAVE TORN OFF AND THERE ARE PIECES ALL OVER THE NORTH EAST SIDE OF LOCATION AND DOWN OFF THE EDGE.		
Corrective Action:	POLICE LOCATION AND SUROUNDING AREA FOR ALL INSULATION/DEBREE PER RULE 606.	Date:	03/04/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	SEISMIC MONITOR EQUIPMENT		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	IS ACCESSABLE		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	SEE HOUSE KEEPING SECTION FOR CORRECTIVE ACTION.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment:	CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.			
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	286776	Type:	WELL	API Number:	071-08984	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: LAST MIT 6/1/2012, WELL HAS BEEN CONVERTED TO A SEISMIC MONITOR WELL.									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
716300581	INSP. PHOTOS	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6933680