

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/19/2025

Submitted Date:

02/25/2025

Document Number:

707801422**FIELD INSPECTION FORM**Loc ID 334632 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, QB		ecmc.inspections@qb-energy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278041	WELL	PR	01/01/2023	GW	045-10828	GMU 33-12C (K33NW)	PR
278042	WELL	PR	01/01/2023	GW	045-10827	GMU 33-13C(K33NW)	PR
278069	WELL	PR	02/01/2011	GW	045-10832	GMU 33-5C (K33NW)	PR
278070	WELL	PR	01/01/2024	GW	045-10831	GMR 33-11 (K33NW)	PR
278071	WELL	PR	11/01/2020	GW	045-10830	GMU 33-4C(K33NW)	PR
278072	WELL	PR	07/01/2023	GW	045-10829	GMU 33-6(K33NW)	PR
284421	WELL	PR	05/01/2010	GW	045-12169	GMU 33-3D(K33NW)	PR
284423	WELL	PR	04/19/2010	GW	045-12170	GMR 33-11D (K33NW)	PR
284426	WELL	PR	05/15/2010	GW	045-12174	GMU 33-3(K33NW)	PR
284427	WELL	PR	02/01/2011	GW	045-12173	GMU 33-12B(K33NW)	PR
284429	WELL	PR	05/09/2010	GW	045-12172	GMU 33-5B (K33NW)	PR
284431	WELL	PR	04/18/2009	GW	045-12171	GMU 33-13B(K33NW)	PR
413111	WELL	PR	04/21/2010	GW	045-18716	GMU 33-11A (K33NW)	PR

General Comment:**ECMC Inspection Report Summary**

On Wednesday 2/19/2025, I, Inspector Scott Ramsey, conducted a routine inspection/audit at Caerus K33NW, at Location # 334632 in Garfield county Colorado.

Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

While there, I observed normal operations. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

This is a summary of inspection report.

LocationOverall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:Comment: [911/970-285-2615](tel:9119702852615)

Corrective Action:

Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Ancillary equipment	# 2		corrective date
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:	Metered		
Corrective Action:		Date:	

Type: Vertical Heated Separator	# 12	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 13	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 13	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 7	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID:	278041	Type:	WELL	API Number: 045-10828 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278042	Type:	WELL	API Number: 045-10827 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278069	Type:	WELL	API Number: 045-10832 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278070	Type:	WELL	API Number: 045-10831 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278071	Type:	WELL	API Number: 045-10830 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	278072	Type:	WELL	API Number: 045-10829 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284421	Type:	WELL	API Number: 045-12169 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID:	284423	Type:	WELL	API Number: 045-12170 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:		Date:		
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	284426	Type:	WELL
API Number:	045-12174	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	284427	Type:	WELL
API Number:	045-12173	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	284429	Type:	WELL
API Number:	045-12172	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	284431	Type:	WELL
API Number:	045-12171	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			
Facility ID:	413111	Type:	WELL
API Number:	045-18716	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Producing		
Corrective Action:		Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Access road lacks stabilization. Maintenance relative to storm water runoff, operators shall consider seasonal factors, such as winter snow cover and spring runoff from snowmelt, to ensure site conditions and controls are adequate and in place to effectively manage storm water.
Places with sparse to no gravel & light compaction are present on lease road and location. Sparse to no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action: **Install, maintain or repair required BMPs**

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707801429	Photo log	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6933763