

Inspection Photos

February 24th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 306987

Inspection Document #: 714001872

La Plata County, CO

Township: NWNE 24 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

2/24/25
+37.007118,-107.556019
17° N



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-09345



Inspection Photos
Location Name: Allison Unit 147S
Location ID: 306987

2/24/25
+37.007221,-107.555797
324° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Oil/lube container at pump jack has no spill prevention/secondary containment.

API #: 067-09345

Inspection Photos
Location Name: Allison Unit 147S
Location ID: 306987



Photo 3. Unused oil and gas equipment at pump jack.



Inspection Photos
Location Name: Allison Unit 147S
Location ID: 306987



Photo 4. Erosion forming on the western edge of the pad.

Inspection Photos
Location Name: Allison Unit 147S
Location ID: 306987

2/24/25
+37.007160,-107.555824
93° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Interim reclamation exclusion fence/sign installed on eastern edge of the pad.

API #: 067-09345

Inspection Photos
Location Name: Allison Unit 147S
Location ID: 306987

2/24/25
+37.007160,-107.555824
26° NE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Interim reclamation area composed of Crested Wheatgrass, Western Wheatgrass, Sand Dropseed and Rabbitbrush.

API #: 067-09345

Inspection Photos
Location Name: Allison Unit 147S
Location ID: 306987



2/24/25
+37.001745,-107.563386
240° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 7. Reference area composed of Juniper, Gambel Oak, Indian Ricegrass and Grama.

API #: 067-09345