

Inspection Photos

February 24th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 306787

Inspection Document #: 714001873

La Plata County, CO

Township: SENW 13 32N 7W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Levey 100
Location ID: 306787



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Levey 100
Location ID: 306787

2/24/25
65° NE



Photo 2. Capacity not displayed at produced water tank labels.

Inspection Photos
Location Name: Levey 100
Location ID: 306787



Photo 3. Rutting occurring on active pad, additional stabilization/grading is needed to minimize degradation to the pad surface.

Inspection Photos
Location Name: Levey 100
Location ID: 306787

2/24/25
113° SE



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. No vehicle tracking observed in the eastern interim reclamation area.

API #: 067-08759

Inspection Photos
Location Name: Levey 100
Location ID: 306787

2/24/25
325° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Interim reclamation area composed of Crested Wheatgrass, Western Wheatgrass, James Galleta and Rabbitbrush.

API #: 067-08759

Inspection Photos
Location Name: Levey 100
Location ID: 306787

2/24/25
210° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Reference area composed of Juniper, Sagebrush and James Galleta.

API #: 067-08759