

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 2/24/2025



Location – Photo #06817




Location – Photo #06816

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 2/24/2025



Location – Photo #06814



Weathered Wellhead Sign – Photo #06818

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 2/24/2025



Open Wellhead Cellar – Photo #06819



Open Wellhead Cellar – Photo #06820

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, CHEVRON-66S96W/20SWSE

Location ID: 335313

Date: 2/24/2025



Rill Erosion on Access Road – Photo #06821



Rill Erosion on Access Road – Photo #06822