

Inspection Photos
Location: Stavelly 1-26
Location ID: 324837
API # 05-061-06394



Photo 1 –Well placard, Wrong API # listed



Photo 2 – Wellhead and Pump Jack

Inspection Photos
Location: Stavelly 1-26
Location ID: 324837
API # 05-061-06394



Photo 3 – Impacted soils at rear of pumping unit

Photo 4 – Lube oil not in containment

Inspection Photos
Location: Stavelly 1-26
Location ID: 324837
API # 05-061-06394



Photo 5 –Tank Battery



Photo 6 – Leaking valve