

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

02/26/2025

Document Number:

710500428**FIELD INSPECTION FORM**Loc ID 324837 Inspector Name: Sanchez, Chris On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 83130Name of Operator: STRACHAN EXPLORATION INCAddress: 992 S 4TH AVE SUITE 100-461City: BRIGHTON State: CO Zip: 80601**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Harms, Jason		Jason@strachanexploration.com	Strachan Exploration
L, Stacy		stacy@strachanexploration.com	Field inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
213033	WELL	PR	09/01/2024	OW	061-06394	STAVELY 1-26	EI
324837	LOCATION	AC			-	STAVELY-618S51W 26SESE	EI

General Comment:This is an Environmental Inspection for the Stavely 1-26 API 05-061-06394

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Wrong API # is listed on the well placard.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/24/2025

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Lube Oil stored on pump jack without containment		
Corrective Action:	Implement or modify BMPs for improved material handling and spill prevention per Rule 1002.f.(2)B	Date:	02/28/2025

Overall Good: ☐

Spills:				
Type	Area	Volume		
Lube Oil	Pump Jack	<= 1 bbl		
Comment:	Stained soils observed at rear of Pump Jack			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: 03/12/2025
Other	Separator	<= 1 bbl		
Comment:	At the time of inspection there was a leak observed on a valve between the separator and tank. Lease Operator, Wayne, who was on a neighboring location was informed of leak on 2/24/2025, 1:28 p.m.			
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.			Date: 02/28/2025

In Containment: Yes _____

Comment: Control and contain spills/releases and clean up per Rule 912.a.

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
------	--	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities				
Facility ID: 213033	Type: WELL	API Number: 061-06394	Status: PR	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				
Facility ID: 324837	Type: LOCATION	API Number: -	Status: AC	Insp. Status: EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12				

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
710500429	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936265