

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2025

Submitted Date:

02/26/2025

Document Number:

707603687**FIELD INSPECTION FORM**Loc ID 428267 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428270	WELL	TA	08/01/2019	OW	123-35297	North Platte 33-34	TA
428276	WELL	TA	01/15/2019	OW	123-35300	North Platte 34-34	TA

General Comment:

This is a WELL inspection.

Well(s): 2: Temporarily Abandoned | TA

Battery: NOT Inspected.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	Location signage posted		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Wellsite(s): 2		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Wellsite(s): 2 Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Compressor	# 0		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:	Wellsite(s): 2		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Wellsite(s): 2 Appears plumbed to surface.		
Corrective Action:		Date:	

Venting:			
Yes/No			

Inspected FacilitiesFacility ID: 428270 Type: WELL API Number: 123-35297 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
OOSLAT applied.
Locked-out, Tagged-out | LOTO.

ECMC records last prod: 12/2018.
Form 4 on file. TA date: 12/03/2018. Approved.
DH-CIBP set.
Form 21-MIT on file. MIT date: 11/12/2020. Approved.
Form 6A on file. Out-of-Svc Designation.
Date Ceased Prod: 08/01/2021. Approved.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/27/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 428276 Type: WELL API Number: 123-35300 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
Disconnected from flowline.
OOSLAT applied.
Locked-out, Tagged-out | LOTO.

ECMC records last prod: 11/2018.
Form 4 on file. TA date: 11/30/2018. Approved.
DH-CIBP set.
Form 21-MIT on file. MIT date: 11/12/2020. Approved.
Form 6A on file. Out-of-Svc Designation.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 10/27/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: End Surf Csg Pressure: 0Comment: Corrective Action: Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
CECMC Inspection Report Synopsis: On MON 02/24/2025 at approximately 13:36 hrs. I, Bret Evins, conducted an onsite inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte/24-34 Pad Location ID: 428267 Well Name(s) & API: Reference: See "Inspected Facilities" section on page 1 of this Field Inspection Report. Location County: Weld County, Colorado Weather: Partly Sunny, damp from prior storm. While there, I observed: Well(s): 2: Temporarily Abandoned TA Battery: NOT Inspected. Routine inspection. *Any Corrective Actions from prior inspections that have not been addressed remain applicable.	evinsb	02/26/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
707603688	Site photo(s)	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936260