

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/26/2025

Submitted Date:

02/26/2025

Document Number:

715800802**FIELD INSPECTION FORM**Loc ID 317830 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1700 LINCOLN ST STE 4550City: DENVER State: CO Zip: 80203**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**16 Number of Comments3 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240033	WELL	PR	09/11/1973	GW	123-07821	SUCKLA G UNIT 1	PR
464785	TANK BATTERY	AC	05/31/2019		-	Suckla G Unit 1 & Unit 2 battery	AC

**General Comment:**[This is a wellsite & tank battery scout card audit followed by a field inspection.](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Faded, peeling hard to read and need to be updated		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	08/06/2024

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Vegetation was left unchecked and is now overgrown & dead around location & equipment.		
Corrective Action:	Comply with Rule 606	Date:	03/06/2025

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	Ancillary equip. has fabricated steel pipe and round stock.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	fabricated steel pipe		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Gas Meter Run	# 1		
Comment:	DCP Gas meter calibration record not current.		
Corrective Action:	Measure gas per Rule 430	Date:	07/06/2024
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Flow Line	# 1	
Comment:	Flow line manifold.	
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment:	electric panel,meter box,transformers	
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	electric motor	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		40.100230,-104.898590
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">shares containment with crude tank</a>					
Corrective Action:				Date:	

Wells Served By Facilities Above

API Number
123-08881
123-07821

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	240033	Type:	WELL	API Number:	123-07821	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR valves open, Most recent PR record in the scout card is from 12-2024.								
Corrective Action:				Date:					
BradenHead									
Date of Last Brhd Test:	05/09/2024		Annual Brhd Completed?	Yes					
Last Brhd Test Results	Initial Surf Csg Pressure:	23	Fluid Type:						
	End Surf Csg Pressure:	0							
Comment:	Plumbed to surface								
Corrective Action:				Date:					
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	464785	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 2-26-2025 at approximately 1345 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Follow up to FIR Doc # 716400195.</p> <p>Operator: KP Kauffman  Location name:  Location ID # 317830  Well Name: Suckla G unit 1  API # 05-123-076821  County: Weld  Weather: Partly Cloudy  Temperature: 54*  Location: Dry</p> <p>While there, I observed a wellsite &amp; tank battery, PR at the time of the inspection. During this inspection, I observed the following compliance issues are delinquent:  430 Gas Measurement: CA date 7-6-2024  605.h tank labels/placards: CA date 8-6-2024</p> <p>During this inspection, I observed the following possible compliance issues now has a CA date:  606 housekeeping: CA 3-6-2025</p> <p>See attached photos.  A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.</p>	revasr	02/26/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715800803	Location photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936314">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6936314</a>