

WELL NAME: FLYING DUTCHMAN 14-35, API #: 071-08908, INSP. # 716300588



PHOTO 1: WELL SIGN



PHOTO 2: LOCATION.





PHOTO 3: WELLHEAD AND EQUIPMENT.





PHOTO 4: THERE IS AN AREA OF IMPACTED SOIL APPEARS TO BE FROM PREVIOUS HYDRO HOSE LEAK THAT APPEARS TO BE FIXED. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 3-5-2025.





PHOTO 5: THERE IS AN AREA OF IMPACTED SOIL NEAR PRIME MOVER ENGINE SKID. Conduct maintenance on equipment (REPAIR LEAKS), cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D CA DATE 3-5-2025.

