

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/20/2025

Submitted Date:

02/20/2025

Document Number:

716300514**FIELD INSPECTION FORM**Loc ID 308174 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 10705Name of Operator: EVERGREEN NATURAL RESOURCES LLCAddress: 1875 LAWRENCE ST STE 1150City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name            | Phone        | Email                      | Comment                         |
|-------------------------|--------------|----------------------------|---------------------------------|
| D DYKE, TRACY           | 719-846-7898 | tracy.dyke@enrllc.com      | <a href="#">Insp. w/ca's</a>    |
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 263369      | WELL | PR     | 03/01/2022  | CBM        | 071-07626 | NUGGETT 44-2  | PR          |

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment: IS ACCESSABLE

Corrective Action:

Date:

Type: Pump Jack

# 1

Comment:

Corrective Action:

Date:

Type: Vertical Separator

# 1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

# 1

Comment:

Corrective Action:

Date:

Type: Deadman # &amp; Marked

# 4

Comment:

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

| Inspected Facilities    |        |                            |      |                        |           |             |    |               |    |
|-------------------------|--------|----------------------------|------|------------------------|-----------|-------------|----|---------------|----|
| Facility ID:            | 263369 | Type:                      | WELL | API Number:            | 071-07626 | Status:     | PR | Insp. Status: | PR |
| Producing Well          |        |                            |      |                        |           |             |    |               |    |
| Comment:                |        | PR                         |      |                        |           |             |    |               |    |
| Corrective Action:      |        |                            |      |                        |           |             |    | Date:         |    |
| BradenHead              |        |                            |      |                        |           |             |    |               |    |
| Date of Last Brhd Test: |        | 11/06/2011                 |      | Annual Brhd Completed? |           |             |    |               |    |
| Last Brhd Test Results  |        | Initial Surf Csg Pressure: |      | 0                      |           | Fluid Type: |    |               |    |
|                         |        | End Surf Csg Pressure:     |      | 0                      |           |             |    |               |    |
| Comment:                |        | FORM 4 ON FILE             |      |                        |           |             |    |               |    |
| Corrective Action:      |        |                            |      |                        |           |             |    | Date:         |    |

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Gravel                  | Fail                  |               |                          |         |
| Ditches          | Pass            | Ditches                 | Fail                  |               |                          |         |
| Compaction       | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: **PHOTO 4: STORMWATER BMP'S HAVE FAILED AND CAUSING STORMWATER TO BYPASS CULVERT AND ERODE THE ROW.**

Corrective Action: **REPAIR OR INSTALL STORMWATER BMP PER RULE1002. CA DATE EXTENDED DUE TO WINTER CONDITIONS.**

Date: 04/01/2025

**Pits:** ☐ NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: 265493 Lat: 37.194962 Long: -104.850309

Reference Point: \_\_\_\_\_ Other: \_\_\_\_\_ Length: \_\_\_\_\_ Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_ Liner Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective \_\_\_\_\_

Date: \_\_\_\_\_

**Fencing:**

Fencing Type: None Fencing Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective \_\_\_\_\_

Date: \_\_\_\_\_

**Netting:**

Netting Type: \_\_\_\_\_ Netting Condition: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective \_\_\_\_\_

Date: \_\_\_\_\_

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: \_\_\_\_\_

Corrective \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404102084    | INSPECTION SUBMITTED | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6928475">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6928475</a> |
| 716300515    | INSP. PHOTOS         | <a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6928465">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6928465</a> |